

5.10	Trace Aromatic Degradation Products .....	80
5.11	Geometry and Efficiency of the TDS-CIS-System .....	81

● **QUANTITATIVE RESULTS FOR POLYSTYRENE AND DISCUSSION**

<b>6</b>	<b>The Way to Quantitation .....</b>	<b>83</b>
6.1	Qualitative Comparisons.....	83
6.2	Establishing 'Total Desorption' or 'Quantitative Extraction' Conditions.....	87
	The Principles of Quantitation .....	87
	Desorption Temperature and Time .....	88
	Test Injections and Calibration.....	89
<b>7</b>	<b>Initial Quantitative Results ('Phase III') .....</b>	<b>91</b>
7.1	General.....	91
7.2	The Three Series of Measurements .....	92
7.3	Product Concentrations vs. the Absorbed Dose.....	93
7.4	Radiation-Chemical Yields (see also Section 9.7).....	94
7.5	2-D-Plot of 1-Phenylethanol vs. Acetophenone Concentrations.....	94
7.6	Re-Evaluating the Desorption Temperature .....	96
7.7	Methyl methacrylate-Acrylonitrile-Butadiene-Styrene (MABS).....	97
7.8	Analytical Problems at the End of 'Phase III' .....	98
7.9	A Strategy for Future Investigations .....	100
7.10	The TDS-Performance-Test.....	101
7.11	Recovery of C <sub>15</sub> - to C <sub>24</sub> -Hydrocarbons .....	102
<b>8</b>	<b>Confirmation of the Quantitative Results ('Phase IV') .....</b>	<b>103</b>
8.1	Qualitative ('Pre-Phase IV') Results .....	103
8.2	Column Selection, Column and System Testing.....	104
8.3	Concentrations Are Under-Estimated after Desorption at 160°C.....	104
8.4	Qualitative Relationships within the 160°C-Data .....	106
8.5	The Various <u>PS 168 N</u> and <u>PS XY</u> Specimens .....	107
8.6	Styrene-Copolymers.....	108