

8.7	The Data Obtained at 200°C Confirm the Earlier ('Phase III') Quantitative Results.....	111
8.8	The Cause of the TDS-Temperature Problem .....	111
8.9	Resumée .....	114
<b>9</b>	<b>Thermal Desorption of PS Solutions with Solvent Evaporation (The 'DSC-Method')</b> .....	<b>115</b>
9.1	Introductory Remarks .....	115
9.2	Principle of the Technique.....	115
9.3	Initial Experiments (Phase III) .....	116
9.4	The Quantitative Series of Measurements (Phase IV).....	118
9.5	Reproducibility for 1-Phenylethanol.....	118
9.6	Relationships Between Various PS-Samples (2D-Plot).....	119
9.7	Radiation-Chemical Yields .....	122
9.8	Direct Injection / Thermal Desorption with the CIS .....	124
9.9	Dissolution-Precipitation.....	125
9.10	On Some Technical Details of, and Problems Associated with, the DSC-Method.....	126
9.11	Analytical Resumée.....	128
<b>10</b>	<b>Identification of Trace Radiolysis Products</b> .....	<b>129</b>
10.1	Desorption of PS Pellets .....	129
10.2	Desorption of PS Powders.....	130
	Objectives .....	130
	Product Identification.....	130
	Chromatograms and Concentration Estimates.....	131
	Trace Products as Radiation Markers ? .....	132
	Resumée.....	134
<b>11</b>	<b>Quantitation of Benzene</b> .....	<b>135</b>
11.1	Qualitative Results .....	135
11.2	Reasons for Quantifying Benzene .....	135
11.3	The Difficulties Associated with Quantifying Benzene in PS .....	136
11.4	The Benzene Method .....	137
11.5	Quantitative Results for Benzene.....	137
11.5	Extrapolated Concentrations at Sterilizing Doses .....	139